









## Dual Tank Bicarb – Standard









### RELATED REPLACEMENT PARTS

| DESCRIPTION  | PART#       | PICTURE   |
|--|-------------|---|
| Propeller Shaft<br>- 316 Stainless Steel                   | EQBICB00471 |     |
| Propeller<br>- Polypropylene                               | EQBICB01923 |    |
| Propeller Set Screw<br>- Stainless Steel                   | EQBICB01920 |    |
| Shaft Coupling<br>- Stainless Steel; one per propeller     | EQBICB00472 |    |
| Coupling Set Screw<br>- Stainless Steel; four per coupling | HWSCSS01920 |  |
| Mixer Motor<br>- 1/4 HP, 115 VAC                           | EQBICB01868 |  |
| Mixer-Motor Power Cord<br>- for Mix/Delivery Bicarb units  | ELPCOO00200 |  |
| MD 100RLT Pump<br>- 1/3 HP, 1 Phase, 115 VAC               | EQPUIW00453 |  |

*Pictures do not reflect the size of the item in relation to the other pictures*

## Dual Tank Bicarb – Standard

### RELATED REPLACEMENT PARTS

| DESCRIPTION  | PART#                           | PICTURE   |
|--|---------------------------------|---|
| 1000 FT Loop Pump<br>- 3/4 HP, 1 Phase, 115 VAC  | <a href="#">EQPUGR00600</a>     |    |
| High Level Proximity Sensor Subassembly, Tank 1<br><i>* For models manufactured from February 2010</i> | <a href="#">EQSUBTNK1HL</a>     |    |
| Low Level Proximity Sensor Subassembly, Tank 1<br><i>* For models manufactured from February 2010</i>  | <a href="#">EQSUBTNK1LL</a>     |    |
| High Level Proximity Sensor Subassembly, Tank 2<br><i>* For models manufactured from February 2010</i> | <a href="#">EQSUBTNK2HL</a>     |   |
| Low Level Proximity Sensor Subassembly, Tank 2<br><i>* For models manufactured from February 2010</i>  | <a href="#">EQSUBTNK2LL</a>     |  |
| High Level Float Switch, Tank 1<br><i>* For models manufactured before February 2010</i>               | <a href="#">EQSUBBICBTNK1FL</a> |  |
| Low Level Float Switch, Tank 1<br><i>* For models manufactured before February 2010</i>                | <a href="#">EQSUBTNK1FL LOW</a> |  |
| High Level Float Switch, Tank 2<br><i>* For models manufactured before February 2010</i>               | <a href="#">EQSUBBICBTNK2FL</a> |  |
| Low Level Float Switch, Tank 2<br><i>* For models manufactured before February 2010</i>                | <a href="#">EQSUBTNK2FL LOW</a> |  |

*Pictures do not reflect the size of the item in relation to the other pictures*

## Dual Tank Bicarb – Standard

### RELATED REPLACEMENT PARTS

| DESCRIPTION   | PART#                          | PICTURE   |
|---|--------------------------------|---|
| Bicarb Unit Control Box   | <a href="#">EQASSYBCB01854</a> |    |
| Bicarb Remote Alarm Box   | <a href="#">EQASSYBCB01709</a> |    |
| Concentrate Regulator Calibration Kit<br>* For calibrating regulators in Floor-Valve-Boxes and Panels<br>* Blue wand is for bicarbonate; Red wand is for acid | <a href="#">EQASSYCC01</a>     |    |
| Flow Control, 2.0 GPM PVC Sch-80  | <a href="#">PLFCS802001</a>    |    |
| Check Valve, 1/2", 316 Stainless-Steel  | <a href="#">PLVASS00846</a>    |  |
| Fuse, 3 Amp, Little-Fuse<br>* For models manufactured before mid-September 2013   | <a href="#">ELLFFS00834</a>    |  |
| Fuse, 2 Amp, Little-Fuse<br>* For models manufactured after mid-September 2013  | <a href="#">ELLFFS00832</a>    |  |
| Flow-Switch, 1", PVC-Clear  | <a href="#">PLFSS800443</a>    |  |

*Pictures do not reflect the size of the item in relation to the other pictures*




## Dual Tank Bicarb – Standard

### RELATED REPLACEMENT PARTS

| DESCRIPTION  | PART#                | PICTURE   |
|--|----------------------|---|
| Volara Foam for Tank Lid, .25" TK x 1.5" W<br>* 6 ft for 60 gallon Tanks<br>* 10 ft for 100 gallon Tanks                 | <b>EQBICB01600</b>   |    |
| 1/2" Red Handle Valve, Plast-O-Matic<br>* For models manufactured before mid-July 2013<br>* Valve B21                    | <b>PLVAS800167</b>   |    |
| 1/2" Red Handle Valve, Asahi<br>* For models manufactured from mid-July 2013<br>* Valve B21                              | <b>PLVAS800167-A</b> |    |
| 3/4" Red Handle Valve, Plast-O-Matic<br>* For models manufactured before mid-July 2013<br>* Valve B8                     | <b>PLVAS800169</b>   |    |
| 3/4" Red Handle Valve, Asahi<br>* For models manufactured from mid-July 2013<br>* Valve B8                               | <b>PLVAS800169-A</b> |   |
| 3/4" Blue Handle Valve, Plast-O-Matic<br>* For models manufactured before mid-July 2013<br>* Valves B6, B7, B9, B10, B15 | <b>PLVAS800170</b>   |  |
| 3/4" Blue Handle Valve, Asahi<br>* For models manufactured from mid-July 2013<br>* Valves B6, B7, B9, B10, B15           | <b>PLVAS800170-A</b> |  |
| 1" Blue Handle Valve, Plast-O-Matic<br>* For models manufactured before mid-July 2013<br>* Valves B11, B12               | <b>PLVAS800172</b>   |  |
| 1" Blue Handle Valve, Asahi<br>* For models manufactured from mid-July 2013<br>* Valves B11, B12                         | <b>PLVAS800172-A</b> |  |

*Pictures do not reflect the size of the item in relation to the other pictures*

## Dual Tank Bicarb – Standard

| DESCRIPTION   | RELATED REPLACEMENT PARTS | PICTURE   |
|---|---------------------------|---|
|   | PART#                     |   |
| 1" Red Handle Valve, Plast-O-Matic<br><i>* For models manufactured before mid-July 2013</i><br><i>* Valves B13, B14</i> | PLVAS800174               |  |
| 1" Red Handle Valve, Asahi<br><i>* For models manufactured from mid-July 2013</i><br><i>* Valves B13, B14</i>           | PLVAS800174-A             |  |
| 1/2" Red Handle, Compact Valve<br><i>* Valves B4, B5</i>  | PLVAS8C0004               |  |

*Pictures do not reflect the size of the item in relation to the other pictures*