RELATED REPLACEMENT PARTS

DESCRIPTION	PART#	PICTURE
Propeller Shaft - 316 Stainless Steel	EQBICB00471	3
Propeller - Polypropylene	EQBICB01923	8
Propeller Set Screw - Stainless Steel	EQBICB01920	(1)
Shaft Coupling - Stainless Steel	EQBICB00472	
Coupling Set Screw - Stainless Steel	HWSCSS01920	(1)
Mixer Motor - 1/4 HP, 115 VAC	EQBICB01868	
Mixer-Motor Power Cord - for Mix/Delivery Bicarb units	ELPCO000200	
MD 100RLT Pump - 1/3 HP, 1 Phase, 115 VAC	EQPUIW00453	

RELATED REPLACEMENT PARTS

DESCRIPTION	PART#	PICTURE
1000 FT Loop Pump - 3/4 HP, 1 Phase, 115 VAC	EQPUGR00600	
High Level Proximity Sensor Subassembly, Tank 1 * For models manufactured from February 2010	EQSUBTNK1HL	
Low Level Proximity Sensor Subassembly, Tank 1 * For models manufactured from February 2010	EQSUBTNK1LL	
High Level Proximity Sensor Subassembly, Tank 2 * For models manufactured from February 2010	EQSUBTNK2HL	
Low Level Proximity Sensor Subassembly, Tank 2 * For models manufactured from February 2010	EQSUBTNK2LL	
High Level Float Switch, Tank 1 * For models manufactured before February 2010	EQSUBBICBTNK1F	
Low Level Float Switch, Tank 1 * For models manufactured before February 2010	EQSUBTNK1FL LO	W
High Level Float Switch, Tank 2 * For models manufactured before February 2010	EQSUBBICBTNK2F	
Low Level Float Switch, Tank 2 * For models manufactured before February 2010	EQSUBTNK2FL LO	w ————————————————————————————————————

RELATED REPLACEMENT PARTS

DESCRIPTION	PART#	PICTURE
Bicarb Unit Control Box	EQASSYBCB01854	The state of the s
Bicarb Remote Alarm Box	EQASSYBCB01709	CONTINUE ALARM CONTIN
Concentrate Regulator Calibration Kit * For calibrating regulators in Floor-Valve-Boxes and Panels * Blue wand is for bicarbonate; Red wand is for acid	EQASSYCC01	
Flow Control, 2.0 GPM PVC Sch-80	PLFCS802001	
Check Valve, 1/2", 316 Stainless-Steel	PLVASS00846	CSSI 1/3
Fuse, 3 Amp, Little-Fuse * For models manufactured before mid-September 2013	ELLFFS00834	
Fuse, 2 Amp, Little-Fuse * For models manufactured from mid-September 2013	ELLFFS00832	
Flow-Switch, 3/4", PVC-Clear	PLFSS800444	

RELATED REPLACEMENT PARTS **DESCRIPTION** PART# **PICTURE** Volara Foam for Tank Lid, .25" TK x 1.5" W **EQBICB01600** * 6 ft for 60 gallon Tanks * 10 ft for 100 gallon Tanks 1/2" Red Handle Valve, Plast-O-Matic PLVAS800167 * For models manufactured before mid-July 2013 * Valve B21 1/2" Red Handle Valve, Asahi PLVAS800167-A * For models manufactured from mid-July 2013 * Valve B21 3/4" Red Handle Valve, Plast-O-Matic **PLVAS800169** * For models manufactured before mid-July 2013 * Valve B8 PLVAS800169-A 3/4" Red Handle Valve, Asahi * For models manufactured from mid-July 2013 * Valve B8 3/4" Blue Handle Valve, Plast-O-Matic **PLVAS800170** * For models manufactured before mid-July 2013 * Valves B6, B7, B9, B10, B15 3/4" Blue Handle Valve, Asahi PLVAS800170-A * For models manufactured from mid-July 2013 * Valves B6, B7, B9, B10, B15 1" Blue Handle Valve, Plast-O-Matic PLVAS800172 * For models manufactured before mid-July 2013 * Valves B11, B12 1" Blue Handle Valve, Asahi PLVAS800172-A

* For models manufactured from mid-July 2013

* Valves B11, B12

RELATED REPLACEMENT PARTS

DESCRIPTION PART# **PICTURE**

1" Red Handle Valve, Plast-O-Matic

* For models manufactured before mid-July 2013

* Valves B13, B14

PLVAS800174



1" Red Handle Valve, Asahi

* For models manufactured from mid-July 2013 * Valves B13, B14

PLVAS800174-A